

Document Number; RS-23-007

To whom it may concern

FUJIMORI KOGYO CO., LTD.

## Certificate of Analysis

Product Code	Product Name	Lot Number	Expiration date
18003	PL Chip Reservoir set for T-TAS 01	4314-PL21	

### Data of Analysis

Test Item	Test Standards	Results
Exterior of PL Chip Reservoir set	No abnormalities in appearance	PASS

### Check items

Check Item	Test Standards	Results
Packaging label	latest version	PASS
IFU	latest version	PASS
	Importer is correctly indicated on IFU	PASS
All products	checked that hard copy of the label is made (per lot)	PASS
	labeled correctly	PASS
	IFU is packed in all products	PASS

Every item above meets the criteria  
Quality Assurance Section Manager

Approved By: *G. Isinami*

Date: *2024/03/22*